


DLBC10 - Cisco Nexus B22DELL





CISCO PID / VID:




N2K - B22DELL - P V01

CISCO SERIAL NUMBER:




FOC1643R06J

MAC ADDRESS



E0:2F:6D:0A:79:00

CLEI CODE



CMUCACHBAA

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

This Class A digital apparatus complies with Canadian ICES-003. Cet appareil numérique de la classe A est conforme à la norme NMB-003 du Canada.

この装置は、クラス A 情報技術装置です。この装置を家庭環境で使用する
と電波妨害を引き起こすことがあります。この場合には使用者が適切な対策
を講ずるよう要求されることがあります。


VCCI-A

警告使用者：
這是甲類的資訊產品，在居住的環境中使用時，可能會造成射頻
干擾，在這種情況下，使用者會被要求採取某些適當的對策。

CUIDADO
PARTES ADENTRO NO REPARÁVEIS
REPARO APENAS POR PESSOAL AUTORIZADO

ATTENTION
ENTRETIEN ET RÉPARATIONS
INTERDITES À L'USAGER
PERSONNEL. TECHNIQUE QUALIPEE

CLASS 1 LASER PRODUCT
PRODUIT LASER DE CLASSE 1
Mfg Date 11/2012




http://cisco-repairs.com

CAUTION
NO OPERATOR SERVICEABLE
PARTS OR REPAIRS
TO QUALIFIED PERSONNEL

KCC - REM - TNY -
N2K - B22DELL

Cisco Systems, Inc.





N906



D33272



Service Tag: 531N6W1



CN - 067MDM - 13740 - 28K - 00HF
Made In China

REV A00

D131240

D130771

10

CISCO PID / VID:

N2K - B22DELL - P V01

CISCO SERIAL NUMBER:

FOC1648R1EH

MAC ADDRESS

E0:2F:6D:E1:5B:40

CLEI CODE

CMUCACHBAA

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

This Class A digital apparatus complies with Canadian ICES-003. Cet appareil numérique de la classe A est conforme à la norme NMB-003 du Canada.

この装置は、クラス A 情報技術装置です。この装置を家庭環境で使用する
と電波妨害を引き起こすことがあります。この場合には使用者が適切な対策
を講ずるよう要求されることがあります。

VCCI-A

警告使用者:

這是甲類的資訊產品，在居住的環境中使用時，可能會造成射頻
干擾，在這種情況下，使用者會被要求採取某些適當的對策。

CUIDADO

PARTES AGENTED NO REPARABLES
POR EL OPERADOR. REFIERA
REPARO A PERSONAL AUTORIZADO.


ATTENTION

ENTRETIEN ET RÉPARATIONS
INTERNES NE SONT AUTORISÉS QU'AU
PERSONNEL TECHNIQUE QUALIFIÉ.


CAUTION

NO OPERATOR SERVICEABLE
PARTS INSIDE. REFER SERVICING
TO QUALIFIED PERSONNEL.

CLASS 1 LASER PRODUCT
PRODUIT LASER DE CLASSE 1
Mfg Date 11/2012



<http://cisco-repairs.com>



KCC - REM - TNY -
N2K - B22DELL

Cisco Systems, Inc.

Revision #3

Created 21 December 2024 00:02:04 by Andy

Updated 17 January 2025 15:59:20 by Andy